

Quota	Quota	Quota	Quota	Quota	Quota
inverteda	inverteda	partenza	partenza	partenza	partenza
1	2	3	4	5	6
131	50.20	X = 20001.6481 Y = 400108.7905	43.95	46.63	
132	50.20	X = 20001.7249 Y = 400114.1089	43.95	46.63	
133	50.20	X = 20001.8004 Y = 400119.4273	43.95	46.63	
134	50.20	X = 20001.8759 Y = 400124.7457	43.95	46.63	
135	50.20	X = 20001.9514 Y = 400130.0641	43.95	46.63	
136	50.20	X = 20002.0269 Y = 400135.3825	43.95	46.63	
137	50.20	X = 20002.1024 Y = 400140.7009	43.95	46.63	
138	50.20	X = 20002.1779 Y = 400146.0193	43.95	46.63	
139	50.20	X = 20002.2534 Y = 400151.3377	43.95	46.63	
140	50.20	X = 20002.3289 Y = 400156.6561	43.95	46.63	
141	50.20	X = 20002.4044 Y = 400161.9745	43.95	46.63	
142	50.20	X = 20002.4799 Y = 400167.2929	43.95	46.63	
143	50.20	X = 20002.5554 Y = 400172.6113	43.95	46.63	
144	50.20	X = 20002.6309 Y = 400177.9297	43.95	46.63	
145	50.20	X = 20002.7064 Y = 400183.2481	43.95	46.63	
146	50.20	X = 20002.7819 Y = 400188.5665	43.95	46.63	
147	50.20	X = 20002.8574 Y = 400193.8849	43.95	46.63	
148	50.20	X = 20002.9329 Y = 400200.0033	43.95	46.63	
149	50.20	X = 20003.0084 Y = 400206.1217	43.95	46.63	
150	50.20	X = 20003.0839 Y = 400212.2401	43.95	46.63	
151	50.20	X = 20003.1594 Y = 400218.3585	43.95	46.63	
152	50.20	X = 20003.2349 Y = 400224.4769	43.95	46.63	
153	50.20	X = 20003.3104 Y = 400230.5953	43.95	46.63	
154	50.20	X = 20003.3859 Y = 400236.7137	43.95	46.63	
155	50.20	X = 20003.4614 Y = 400242.8321	43.95	46.63	
156	50.20	X = 20003.5369 Y = 400248.9505	43.95	46.63	
157	50.20	X = 20003.6124 Y = 400255.0689	43.95	46.63	
158	50.20	X = 20003.6879 Y = 400261.1873	43.95	46.63	
159	50.20	X = 20003.7634 Y = 400267.3057	43.95	46.63	
160	50.20	X = 20003.8389 Y = 400273.4241	43.95	46.63	
161	50.20	X = 20003.9144 Y = 400279.5425	43.95	46.63	
162	50.20	X = 20003.9899 Y = 400285.6609	43.95	46.63	
163	50.20	X = 20004.0654 Y = 400291.7793	43.95	46.63	
164	50.20	X = 20004.1409 Y = 400297.8977	43.95	46.63	
165	50.20	X = 20004.2164 Y = 400304.0161	43.95	46.63	
166	50.20	X = 20004.2919 Y = 400310.1345	43.95	46.63	
167	50.20	X = 20004.3674 Y = 400316.2529	43.95	46.63	
168	50.20	X = 20004.4429 Y = 400322.3713	43.95	46.63	
169	50.20	X = 20004.5184 Y = 400328.4897	43.95	46.63	
170	50.20	X = 20004.5939 Y = 400334.6081	43.95	46.63	
171	50.20	X = 20004.6694 Y = 400340.7265	43.95	46.63	
172	50.20	X = 20004.7449 Y = 400346.8449	43.95	46.63	
173	50.20	X = 20004.8204 Y = 400352.9633	43.95	46.63	
174	50.20	X = 20004.8959 Y = 400359.0817	43.95	46.63	
175	50.20	X = 20004.9714 Y = 400365.2001	43.95	46.63	
176	50.20	X = 20005.0469 Y = 400371.3185	43.95	46.63	
177	50.20	X = 20005.1224 Y = 400377.4369	43.95	46.63	
178	50.20	X = 20005.1979 Y = 400383.5553	43.95	46.63	
179	50.20	X = 20005.2734 Y = 400389.6737	43.95	46.63	
180	50.20	X = 20005.3489 Y = 400395.7921	43.95	46.63	
181	50.20	X = 20005.4244 Y = 400401.9105	43.95	46.63	
182	50.20	X = 20005.5000 Y = 400408.0289	43.95	46.63	
183	50.20	X = 20005.5755 Y = 400414.1473	43.95	46.63	
184	50.20	X = 20005.6510 Y = 400420.2657	43.95	46.63	
185	50.20	X = 20005.7265 Y = 400426.3841	43.95	46.63	
186	50.20	X = 20005.8020 Y = 400432.5025	43.95	46.63	
187	50.20	X = 20005.8775 Y = 400438.6209	43.95	46.63	
188	50.20	X = 20005.9530 Y = 400444.7393	43.95	46.63	
189	50.20	X = 20006.0285 Y = 400450.8577	43.95	46.63	
190	50.20	X = 20006.1040 Y = 400456.9761	43.95	46.63	
191	50.20	X = 20006.1795 Y = 400463.0945	43.95	46.63	
192	50.20	X = 20006.2550 Y = 400469.2129	43.95	46.63	
193	50.20	X = 20006.3305 Y = 400475.3313	43.95	46.63	
194	50.20	X = 20006.4060 Y = 400481.4497	43.95	46.63	
195	50.20	X = 20006.4815 Y = 400487.5681	43.95	46.63	
196	50.20	X = 20006.5570 Y = 400493.6865	43.95	46.63	
197	50.20	X = 20006.6325 Y = 400500.0049	43.95	46.63	
198	50.20	X = 20006.7080 Y = 400506.3233	43.95	46.63	
199	50.20	X = 20006.7835 Y = 400512.6417	43.95	46.63	
200	50.20	X = 20006.8590 Y = 400518.9601	43.95	46.63	
201	50.20	X = 20006.9345 Y = 400525.2785	43.95	46.63	
202	50.20	X = 20007.0100 Y = 400531.5969	43.95	46.63	
203	50.20	X = 20007.0855 Y = 400537.9153	43.95	46.63	
204	50.20	X = 20007.1610 Y = 400544.2337	43.95	46.63	
205	50.20	X = 20007.2365 Y = 400550.5521	43.95	46.63	
206	50.20	X = 20007.3120 Y = 400556.8705	43.95	46.63	
207	50.20	X = 20007.3875 Y = 400563.1889	43.95	46.63	
208	50.20	X = 20007.4630 Y = 400569.5073	43.95	46.63	
209	50.20	X = 20007.5385 Y = 400575.8257	43.95	46.63	
210	50.20	X = 20007.6140 Y = 400582.1441	43.95	46.63	
211	50.20	X = 20007.6895 Y = 400588.4625	43.95	46.63	
212	50.20	X = 20007.7650 Y = 400594.7809	43.95	46.63	
213	50.20	X = 20007.8405 Y = 400601.0993	43.95	46.63	
214	50.20	X = 20007.9160 Y = 400607.4177	43.95	46.63	
215	50.20	X = 20007.9915 Y = 400613.7361	43.95	46.63	
216	50.20	X = 20008.0670 Y = 400620.0545	43.95	46.63	
217	50.20	X = 20008.1425 Y = 400626.3729	43.95	46.63	
218	50.20	X = 20008.2180 Y = 400632.6913	43.95	46.63	
219	50.20	X = 20008.2935 Y = 400639.0097	43.95	46.63	
220	50.20	X = 20008.3690 Y = 400645.3281	43.95	46.63	
221	50.20	X = 20008.4445 Y = 400651.6465	43.95	46.63	
222	50.20	X = 20008.5200 Y = 400657.9649	43.95	46.63	
223	50.20	X = 20008.5955 Y = 400664.2833	43.95	46.63	
224	50.20	X = 20008.6710 Y = 400670.6017	43.95	46.63	
225	50.20	X = 20008.7465 Y = 400676.9201	43.95	46.63	
226	50.20	X = 20008.8220 Y = 400683.2385	43.95	46.63	
227	50.20	X = 20008.8975 Y = 400689.5569	43.95	46.63	
228	50.20	X = 20008.9730 Y = 400695.8753	43.95	46.63	
229	50.20	X = 20009.0485 Y = 400702.1937	43.95	46.63	
230	50.20	X = 20009.1240 Y = 400708.5121	43.95	46.63	
231	50.20	X = 20009.1995 Y = 400714.8305	43.95	46.63	
232	50.20	X = 20009.2750 Y = 400721.1489	43.95	46.63	
233	50.20	X = 20009.3505 Y = 400727.4673	43.95	46.63	
234	50.20	X = 20009.4260 Y = 400733.7857	43.95	46.63	
235	50.20	X = 20009.5015 Y = 400740.1041	43.95	46.63	
236	50.20	X = 20009.5770 Y = 400746.4225	43.95	46.63	
237	50.20	X = 20009.6525 Y = 400752.7409	43.95	46.63	
238	50.20	X = 20009.7280 Y = 400759.0593	43.95	46.63	
239	50.20	X = 20009.8035 Y = 400765.3777	43.95	46.63	
240	50.20	X = 20009.8790 Y = 400771.6961	43.95	46.63	
241	50.20	X = 20009.9545 Y = 400778.0145	43.95	46.63	
242	50.20	X = 20010.0300 Y = 400784.3329	43.95	46.63	
243	50.20	X = 20010.1055 Y = 400790.6513	43.95	46.63	
244	50.20	X = 20010.1810 Y = 400796.9697	43.95	46.63	
245	50.20	X = 20010.2565 Y = 400803.2881	43.95	46.63	
246	50.20	X = 20010.3320 Y = 400809.6065	43.95	46.63	
247	50.20	X = 20010.4075 Y = 400815.9249	43.95	46.63	
248	50.20	X = 20010.4830 Y = 400822.2433	43.95	46.63	
249	50.20	X = 20010.5585 Y = 400828.5617	43.95	46.63	
250	50.20	X = 20010.6340 Y = 400834.8801	43.95	46.63	
251	50.20	X = 20010.7095 Y = 400841.1985	43.95	46.63	
252	50.20	X = 20010.7850 Y = 400847.5169	43.95	46.63	
253	50.20	X = 20010.8605 Y = 400853.8353	43.95	46.63	
254	50.20	X = 20010.9360 Y = 400860.1537	43.95	46.63	
255	50.20	X = 20011.0115 Y = 400866.4721	43.95	46.63	
256	50.20	X = 20011.0870 Y = 400872.7905	43.95	46.63	
257	50.20	X = 20011.1625 Y = 400879.1089	43.95	46.63	
258	50.20	X = 20011.2380 Y = 400885.4273	43.95	46.63	
259	50.20	X = 20011.3135 Y = 400891.7457	43.95	46.63	
260	50.20	X = 20011.3890 Y = 400898.0641	43.95	46.63	
261	50.20	X = 20011.4645 Y = 400904.3825	43.95	46.63	
262	50.20	X = 20011.5400 Y = 400910.7009	43.95	46.63	
263	50.20	X = 20011.6155 Y = 400917.0193	43.95	46.63	
264	50.20	X = 20011.6910 Y = 400923.3377	43.95	46.63	
265	50.20	X = 20011.7665 Y = 400929.6561	43.95	46.63	
266	50.20	X = 20011.8420 Y = 400935.9745	43.95	46.63	
267	50.20	X = 20011.9175 Y = 400942.2929	43.95	46.63	
268	50.20	X = 20011.9930 Y = 400948.6113	43.95	46.63	
269	50.20	X = 20012.0685 Y = 400954.9297	43.95	46.63	
270	50.20	X = 20012.1440 Y = 400961.2481	43.95	46.63	
271	50.20	X = 20012.2195 Y = 400967.5665	43.95	46.63	
272	50.20	X = 20012.2950 Y = 400973.8849</			