

UBICAZIONE PIEZOMETRI

	X	Y	Quota testa piezometro
CET2/3_PZ1_Sup	1626073	4755430	5,199
CET2/3_PZ2_Sup	1626149	4755485	5,079
CET2/3_PZ3_Sup	1626243	4755313	5,097
CET2/3_PZ4_Sup	1626188	4755277	5,032
CET2/3_PZ5_Sup	1626094	4755275	5,085
CET2/3_PZ6_Sup	1626253	4755564	5,189
CET2/3_PZ7_Sup	1626246	4755473	5,154

	X	Y	Quota testa piezometro
CET2/3_PZ1_Inf	1626072	4755428	5,158
CET2/3_PZ2_Inf	1626148	4755487	4,982
CET2/3_PZ3_Inf	1626242	4755310	5,156
CET2/3_PZ4_Inf	1626189	4755274	5,087
CET2/3_PZ5_Inf	1626096	4755274	5,101
CET2/3_PZ6_Inf	1626252	4755567	5,17
CET2/3_PZ7_Inf	1626246	4755470	5,092