


Fault Tree Diagrams

71653-Sernano



Mancato intervento livellostato e mancato intervento operativo
 GT95
 Q=2,3E-2 w=4,5E-2

